SN 5/88

## SAFETY NOTICE

## GROUNDING OF G.Q. SECURITY AND CONICAL (SAC) RESERVES

Following a directive from the C.A.A. (see attached paper). All G.Q. Security Aero-Conical (SAC) Reserve Parachutes, manufactured in the USA, Model Number: 79A1684 - ( ) approved under U.S. TSO C23b, have been grounded by an Emergency Airworthiness Directive issued by the Federal Aviation Administration (FAA). This ground therefore applies World Wide.

Jumpers are reminded that this does not apply to G.Q. SAC reserves manufactured in the U.K.

It is hoped that more information will be available shortly.

Any queries, please contact either JNCSO.

Tony Butler

JOINT NATIONAL COACH &
SAFETY OFFICER

17th March 1988

Distribution:

All CCI's Clubs Advanced Riggers Civil Aviation Authority
Brabazon House
Redhill
Surrey RH1 1SQ
Telephone Redhill (0737) 765966
Telex 27100 Telegrams & Cables Bordair Redhill
Facsimile Group 3 Redhill (0737) 761411



British Parachute Association Kimberley House 47 Vaughan Way Leicester LE1 4SG 9/97/CtAw/314

16 March 1988

For the attention of Mr Tony Butler

Dear Sirs

FAA EMERGENCY AIRWORTHINESS DIRECTIVE 88-05-08 G Q SECURITY PAPACHUTES INC MODEL NO 79A1684 - ( ) PARACHUTE CANOPIES, APPROVED UNDER TSO C23b. DETERIORATING CANOPY MATERIAL

This letter transmits a copy of FAA Emergency Airworthiness Directive 88-05-08 in respect of the above mentioned parachute.

In accordance with Airworthiness Notice No.36 this Airworthiness Directive is mandatory in the United Kingdom.

Yours faithfully

R J TEW

Aircraft Maintenance and Approvals

## EMERGENCY AIRWORTHINESS DIRECTIVE



U.S. Department of Transportation Federal Aviation Administration

AVIATION STANDARDS NATIONAL FIELD OFFICE OKLAHOMA CITY, OKLAHOMA 73125

MARCH 7, 1988

This Priority Letter AD is necessary because reports have been received that certain parachute canopies manufactured by G Q Security Parachutes, Inc., and approved under TSO C23b were found to have deteriorating material. This condition, if not corrected, could result in a torn canopy, which could prevent safe descent of the parachute user.

Since this condition is likely to exist or develop on other canopies of this same type design, this AD requires removal or obliteration of the TSO C23b marking and removal of the canopy from service.

Pursuant to the authority of Sections 313 and 601 of the Federal Aviation Act of 1958, delegated to me by the Administrator, the following Priority Letter Airworthiness Directive (AD) 88-05-08, applicable to G Q Security Parachutes, Inc., Model No., 79A1684-() parachute canopies\_approved under -TSO C23b, is issued and is effective immediately upon receipt:

Priority Letter 88-05-08 G C SECURITY PARACHUTES, INC.: issued March 7, 1988. Applicable to Model No. 79A1684-() parachute canopies, approved under TSO C23b.

unless indicated, Compliance is required as

accomplished.

To prevent the failure of a parachute canopy due to

deteriorating canopy material, accomplish the following:

- A. Prior to further use, remove or obliterate the TSO C23b marking from the parachute canopy, and remove the canopy from service.
- Upon request, an alternate means of compliance with the requirements of this AD which provide an acceptable level of B. safety, may be used when approved by the Manager, Western Aircraft Certification Office, FAA, Northwest Mountain Region.

This priority letter AD 88-05-08, dated March 7, 1988 is

effective immediately upon receipt.

## FOR FURTHER INFORMATION CONTACT:

Walter Eierman, Western Aircraft Certification Office, ANM-173W, FAA, Northwest Mountain Region, P.O. Box 92007, Worldway Postal Center, Los Angeles, California telephone (213) 297-1388.