



# SAFETY INFORMATION

1/91

## FXC SAFETY INFORMATION

There is a possibility that the hose lengths on some FXCs are not compatible with other FXC units. On firing the ripcord pin(s) may not clear the loops. When a hose change is required, consult the manufacturers or service organisation to ensure compatibility.

In all circumstances when fitting or re-fitting an FXC to equipment, a test firing should be carried out to ensure the ripcord pin(s) clear the loop(s) allowing the container to open.

John Hitchen  
National Coach & Safety Officer

14th January 1991