




SAFETY INFORMATION

5/93

CUT-AWAY PAD CABLE HOUSINGS



The BPA has been informed of a number of cut-away teflon cables that are being damaged by a poor finish to the inside of the cable housing near to the cutaway pad*. Which can result in a hard pull.

Parachutists should check their housings to ensure that the ends (inside and out) are smooth. *

Tony Butler
Technical Officer

27th August 1993

Distribution

CCIs
Council
Advanced Riggers
STC Mailing
Sport Parachutist
File