



SAFETY INFORMATION

1/94

RISER BRAKE LOCKING RINGS

Some ram air canopy risers are still being found fitted with brake locking rings of inadequate strength, specifically "Baby" D Rings (Paragear catalogue No. H219).

This type of ring could fail on canopy deployment leading to a loss of the steering line and possibly causing a canopy malfunction.

Parachutists should ensure that only Rings of sufficient load bearing capacity are installed in this vital area.

If you have any doubt ask your CCI or Rigger.

Tony Butler
Technical Officer

28th January 1994

Distribution

Clubs
Riggers
STC Mailing
Council
Ola Soyinka
File