



SAFETY INFORMATION

2/97

3 Ring Risers

It has become apparent that the middle ring on some three ring systems may have considerable damage caused by "ring slap". All parachutists should check their equipment and seek advice from their CCI or Rigger should they find excessive damage. If you are not sure ask!.

All jumpers are reminded of the importance of regular maintenance and service of 3- rings.

Paul Applegate
Chairman Riggers Committee

25th June 1997

Distribution

CCIs
Riggers
Council
STC Mailing
Sport Parachutist
File