



SAFETY INFORMATION

1/19

CYPRES AAD SERVICE LIFE & MAINTAINANCE

In January 2019 Airtec GmbH & Co.Kg Safety Systems, reviewed and changed their maintenance policy from highly recommended to voluntary for any units manufactured after the 1st of January 2016. This change is based on information gathered from data of Cypres 2 units in the field, which undertook technical changes in 2014.

Based on this information, Airtec have now confirmed to us, that these devices have been technically designed in such a way that, according to their current assessment, they can last their entire service life without maintenance.

Therefore, Safety Information 2/16 and 1/17 are rescinded and the following extract of the **Cypres 2 Users Guide** now applies:

Page 55, Paragraph 14.1 Versioning

*For units with DOM 12/15 and earlier the maintenance is **mandatory** to be performed 4 and 8 years after the original DOM. Service Life is 12.5 years.*

For units made in 2016 the maintenance can be performed on a voluntary basis 4 and 8 years after original DOM. Service Life is 12.5 years.

For units with DOM 01/17 and later the maintenance can be performed on a voluntary basis 5 and 10 years after the original DOM. Service Life is 15.5 years.

5 April 2019

Jeff Montgomery
Safety & Technical Officer

Pete Sizer
Chairman Riggers' Subcommittee

Distribution

CIs
Council
Riggers
STC Mailing
Skydive – The Mag
File