



# SAFETY INFORMATION

1/04

## TEFLON COATED CLOSING PINS

Recently a 'teflon pin' became detached from the bridle during use.

Users of such 'pins', commonly found on Tandem bridles, static line bridles and some 'experienced' kit, should regularly inspect the pins.

Noting:       The security of the swage.

                  The condition of the material attachment.

                  The condition of the coating on the 'pin'.

Tony Butler  
Technical Officer  
On behalf of the  
Riggers Committee

14<sup>th</sup> June 2004

### Distribution

CCIs  
Council  
Riggers  
STC Mailing  
Skydive – The British Mag  
File